






Figure S-2
Flood Hazards



-  100-Year Floodplain
-  500-Year Floodplain
-  Drainage Basins and Channels
-  San Antonio Creek Dam Failure Inundation Area

Source: Earth Consultants International, Inc. 2006